

Bertolucci, Alexander

To: Allain, Joshua; Isaiah A. Fishman
Subject: RE: Prestige Update?

From: Allain, Joshua <JAllain@mountprospect.org>
Sent: Friday, March 28, 2025 3:51 PM
To: Isaiah A. Fishman <ifishman@mpslaw.com>; Bertolucci, Alexander <abertolucci@mountprospect.org>
Subject: FW: Prestige Update?

From: Joe Pesoli <JCP@prestigefeed.com>
Sent: Wednesday, April 22, 2020 9:58 AM
To: Allen, Brandon <BAllen@mountprospect.org>
Subject: RE: Prestige Update?

Brandon-

I hope you are well. This entire situation has been pretty crazy. As I am sure you have seen on the news we are seeing major disruptions to the food processing industry and companies like Smithfield and JBS (large customers of Prestige's) are shutting down plants left and right. It has impacted our business greatly.

We are in the final stages of ordering our carbon filter air filtration system. We are hoping it will be delivered to our facility in 8-10 weeks, but it is coming from a manufacturer in Canada, so with Covid-19 who knows when it will really be here. We will be re-appropriating the duct work from the cyclones to connect directly to this roof top carbon filter unit. We will no longer have air going straight out the cyclones into the atmosphere.

We will continue to use our atomization (vapor inside the new duct work with spray nozzles). With the new location inside the duct work they will be easier for us to clean as well as protected from the elements which was a point of issue during the winter months with our temporary set up.

We will also be re-appropriating the vaporization pipe work which currently forms a halo above the cyclones and on our roof to be placed around the new carbon filter box so that we can again treat the air after it is filtered.

Basically we will have a 3 step process going forward.

1. Applying vapor through atomization inside the new closed duct work from the cyclones to the air filter system. Easier to clean, protected from the elements and more efficient as it will be applied in a confined space reducing loss of efficiency for wind, rain, etc...
2. Carbon filtration. The unit has 24 carbon filters that will need to be changed every 6 months. We purchased 3 sets of 24 so that we have the ability to change them more often if needed without delay. We can change all filters in about 45 mins per the manufacturer and will be part of regular scheduled maintenance.
3. Vaporization on the rooftop and around the carbon filtration system

Attached is a rough sketch. Once I have all the formal drawings, etc... we will provide that.

Right now we are not running the plant, so odor issues and complaints won't be problem.

I appreciate your patience and the patience of the VoMP while we try to navigate this solution though Covid-19.

Stay safe.

From: Allen, Brandon <BAllen@mountprospect.org>

Sent: Monday, April 20, 2020 4:04 PM

To: Joe Pesoli <JCP@prestigefeed.com>

Subject: Prestige Update?

Joe,

Just checking how things were going. I'm sure, as with everyone, you guys have had some setbacks due to the current State shut down. Hope all is well with you and your family.

Thanks,

Brandon

Special Notice to our Customers

During the health emergency, our Village Hall is closed to the public. Staff is on a rotating schedule at Village Hall and working remotely to maintain the services to the public. This rotating schedule of staff will allow for the continued operation of Village services during the emergency.

Currently, we are processing permit applications, performing plan reviews, performing most inspections, and responding to customer inquiries. Permit applications are allowed electronically via email to tlewin@mountprospect.org or permit@mountprospect.org. We also have an online portal which is available at <https://www.mountprospect.org/business/licenses-and-permits/building-permits>

For any technical or questions on inspections, please email building@mountprospect.org

Any questions or if you need help, please let us know. We are here for you during these challenging times.

Scanned by the Symantec Email Security.cloud service.



