



NOTES:

1. MATCH INVERT OF EXISTING PIPE LINING AND NEW SEGMENT OF PIPE.
2. IF THE MAIN LINE SEWER IS CRACKED OR DAMAGED, THE CONTRACTOR IS RESPONSIBLE FOR IDENTIFYING GOOD HOST PIPE TO ATTACH MISSION COUPLINGS. THE CONTRACTOR IS RESPONSIBLE FOR UP TO 10 FT. OF PIPE. IF GREATER THAN 10 FT., THE VILLAGE MUST BE CONTACTED.
3. IF AN UNIDENTIFIED TAP IS DISCOVERED OR WITHIN 6" OF AN EXISTING TAP, THE VILLAGE MUST BE CONTACTED TO DETERMINE IF ADDITIONAL PIPE MUST BE REPLACED.

<b>Village of Mount Prospect</b>	
Public Works Department 1700 W Central Rd	
<b>MAIN LINE REPAIR &amp; SERVICE ABANDONMENT DETAIL</b>	
Scale: None	Last Revised: 8-09