

NOTE: MATCH INVERT OF EXISTING PIPE LINING AND NEW SEGMENT OF PIPE.

Village of Mount Prospect

Public Works Department 1700 W. Central Rd.

CIPP REPAIR DETAIL Last Revised: 2-08

H:\Misc\Eng\Details\CIPP REPAIR DETAIL.dwg