

Prestige Feed – Village of Mount Prospect

Monitoring Locations

Date: 1/9/2025

Field Operator Matthew Drabik

Wellness Check MTD

Randomize order of observations, collecting readings at all locations

Locations		Time	Wind Direction	Wind Speed	Temp. °F	Humidity	Barometric Pressure	Weather (Precip?)	Scentometer Reading or Non-Detect	Odor Description Prestige Odor
Locations	#									
431 Lakeview Ct, Mt P Prestige Parking Lot	N M-1	2017	SW	3.8	30.0	45.2	29.47	N	2	Prestige
431 Lakeview Ct, Mt P Prestige Parking Lot	E M-2	2022	SW	2.2	30.2	41.8	29.47	N	<2	Prestige
431 Lakeview Ct, Mt P Prestige Parking Lot	S M-3	2010	SW	1.3	31.6	42.0	29.48	N	ND	---
431 Lakeview Ct, Mt P Prestige Parking Lot	W M-4	2014	WSW	2.0	30.6	46.9	29.47	N	ND	---
1601 Feehanville Drive, Mt P (Mizkah American/ Park View Montessori)	M-5	2003	SW	2.2	25.5	44.7	29.47	N	15	Prestige
1660 Feehanville Drive, Pt P (Professional Endodontics of IL)	M-6	1951	SW	1.1	32.3	48.3	29.49	N	4	Prestige
1471 E Business Center Dr, Mt P (DeliverCareRx Pharmacy)	M-7	1957	SW	4.1	25.3	52.1	29.48	N	ND	---
E Lowden Ln & Yates Ln, Mt P (South of the Facility)	M-8	1925	SW	3.4	28.1	43.1	29.47	N	ND	---
E Lowden Ln & N Stratton Ln, Mt P (Southwest of the Facility)	M-9	1933	WSW	5.5	25.3	45.7	29.48	N	ND	---
1513 Mitchell Ln, Mt P (Inzerillo Residence)	M-10	1929	WSW	1.9	28.6	47.4	29.47	N	ND	---
676 Middleton Ln, DP (Stillmaker Residence)	M-11	1942	SW	4.0	28.6	44.4	29.49	N	ND	---

Prestige Feed – Village of Mount Prospect
Monitoring Locations

Date: 1/9/2025

Field Operator Matthew Drabik

Randomize order of observations, collecting readings at all locations

Wellness Check MTD

Locations		Time	Wind Direction	Wind Speed	Temp. °F	Humidity	Barometric Pressure	Weather (Precip?)	Scentometer Reading or Non-Detect	Odor Description Prestige Odor
Locations	#									
650 Dursey Ln, DP (Merza Residence) 660 Dursey Ln, DP (Kulaga Residence)	M-12	1947	WSW	4.9	26.6	58.8	29.49	N	ND	---
774 Mark Ave, DP (Pfisterer Residence)	M-13	1920	SE	1.5	34.2	44.9	29.47	N	<2	---
720 E. Central Rd, DP Steve's Automotive Repair Center	M-14	1915	SW	4.4	27.1	35.4	29.47	N	<2	---
630 Kylemore Dr, DP (Thomas & Kuriakose Residence)	M-15	1937	SSW	6.3	29.9	52.2	29.49	N	ND	---